AE 485 S
Jumpers and Programming Points

Reset Contact Fields

Position for D 1 and SW 411 (countries with CB-Band only)

Position of D 2 (Germany and countries where extension allowed) (factory installed)

position of SW 412 (belongs to D 2)

